

Engineering Bulletin

Bulletin No: EB-05-004 30 September 2005
Equipment: Part No: 8002238-10 Rev F/E/D/C/B/A/-
Description: CCA Video Output
Manufacturer: BAE Systems
Serial No: 010077, 010078, 010079, 010101,
 010075, 010122, 010111, 020017,
 020026, 020063, 030006, 040061,
 040060
Subsystem: Part No: 8002219-10/-20/-30/-40

Model No: RSP-1105

Description: Assembly Radar Signal Processor
Symptom: Targets outside the selected Acquisition Window may be processed during Automatic Acquisition. Furthermore, a reported false address results in hitting on noise approximately 1,000 yards outrange of the target.
Solution: If you are experiencing this problem and would like it corrected, the Video Output CCA may be returned to BAE Systems. Specifically, firmware FW8002238-003C must be updated.
Please contact our customer support representative for further information regarding this bulletin.

Technical Services
Electronic Systems Division
557 Mary Esther Cut-Off
Ft. Walton Beach, FL 32548-4090
Attn: Diana DePrisco, Customer Support
Email: diana.deprisco@baesystems.com
Phone: 850-664-1313
Fax: 850-664-1365